

HONDA FJS600 Silver Wing

Parts list for CC 4480 kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCSU 400C	Computer
2	4		8g x 3/8" self tap screw
		<u>MCS 4482</u>	<u>Vacuum actuator assembly</u>
3	1	MCS 574	Vacuum actuator (triple solenoid)
4	1	MCS 4482A	Actuator mounting bracket
	3		6g x 3/8" self tap screw
		<u>MCS 4487</u>	<u>Vacuum hose assembly</u>
5	2	MCS 032	Vacuum stop valve
6	4	MCS 031	Vacuum 'T' connector
7	2	MCS 052	Vacuum restrictor
8			4mm Vacuum hose
9	1	MCS 4481	Wiring loom
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			Speed sensor (co-axial wire)
d			Actuator plug (4 pin)
e			Power & brake sensor (orange and grey wires)
f			Ground connector (black wire)
g			Switch plug (6 pin)
		<u>MCS 4484</u>	<u>Control switch assembly</u>
10	1	MCS 820	Control Switch
11	1	MCS 830A	Switch bracket
	4		4 gauge x 1/2" pan head SS self tap screw
	1		100mm cable tie
		<u>MCS 4485</u>	<u>Cable Interface Unit (CIU) assembly</u>
12			
13	1	MCS 4485A	CIU housing
14	1	MCS 003F	Actuator spool
15	1	MCS 4486	Dual spool
16	1	MCS 003H	Bush
17	1	MCS 003K	End Cap
18	1		M5 x 50 counter sunk metal thread screw
19	1		M5 nut
20	3		5mm flat washer
21	1	MCS 003X	Mounting clip
22	1		M5 Nyloc nut
23	1		M4 x 10 pan head screw (actuator cable retainer)
24	1	MCSCC 150	Carburettor cable
	1	MCS 4488	Wiring grommet
	3	MCS 049	Cable tie mount pad
	15		150mm cable ties
	5		200mm cable ties

Information, Set up and Operation Manual
 Operation and User Manual
 Installation Manual
 Trouble shooting guide

